

STANDING WATER - NOT A PROBLEM WITH BELZONA

CUSTOMER

Air Force Base, Texas - USA

APPLICATION DATE

March 2005

APPLICATION SITUATION

Stainless steel gutters

PROBLEM

Leaking gutters

PRODUCTS

Belzona® 3111 (Flexible Membrane)

Belzona® 3921 (GSC Surface Conditioner)

Belzona® 9311 (Membrane Reinforcing Sheet)

SUBSTRATE

Stainless Steel

APPLICATION METHOD


Application was carried out in accordance with Belzona Know-How System Leaflet RPA-7.

BELZONA FACTS

Gutters on roof were coated with "low bid" product. Subsequent leaks soon appeared. Client wanted a more durable solution and chose Belzona once again.

PICTURES

1. Gutters conditioned with Belzona® 3921 and seams coated with Belzona® 3111.
2. Seams coated with Belzona® 3111.
3. First coat of Belzona® 3111.
4. Second coat of Belzona® 3111.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>