

BELZONA® 2111 (D&A HI BUILD ELASTOMER) SAVES UTILITY

CUSTOMER

Power Authority, San Antonio, Texas USA

APPLICATION DATE

2002

APPLICATION SITUATION

Rubber lined lime slurry tank

PROBLEM

Inspection revealed severe corrosion in spots on floor. Customer needed fast, cost effective repair.

PRODUCTS

Belzona® 2111 (D&A Hi Build Elastomer)

Belzona® 2911 (QD Conditioner)

SUBSTRATE

Rubber

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-3.

BELZONA FACTS

Hot vulcanization and liner replacement had been considered but were judged too time consuming and costly. Belzona® 2111 was chosen for its great abrasion and chemical resistance, as well as its ease of application. Repair still in excellent condition after three years of service.

PICTURES

1. Lime slurry tank showing corrosion in rubber liner
2. Another view of corrosion
3. Close up view of corrosion
4. Belzona® 2111 patch complete



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve