

BELZONA SEALS COOLING TOWER AT GOVERNMENT BUILDING

CUSTOMER

Municipal Building - Ontario, Canada

APPLICATION DATE

April 2005

APPLICATION SITUATION

Cooling Tower

PROBLEM

Corrosion and leaks particularly at joints.

PRODUCTS

Belzona® 1221 (Super E-Metal)

Belzona® 5811 (Immersion Grade)

SUBSTRATE

Galvanized Steel

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-15.

BELZONA FACTS

Belzona® 5811 is ideal for the protection of cooling tower basins. Belzona® 1221 was used to repair areas more severely damaged prior to the coating application.

PICTURES


1. Exterior image of cooling tower
2. Interior image of the problematic cooling tower
3. Belzona 5811 applied
4. Another shot of the cooling tower, ready for service



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

