

BELZONA PERFORMS A CLASSIC REPAIR

CUSTOMER

Motor Enthusiast, Cheshire, England

APPLICATION DATE

April 2005

APPLICATION SITUATION

Engine casing on vintage car

PROBLEM

A small crack had developed in the 2.8 litre engine casing of this 1951 David Brown Lagonda.

PRODUCTS

Belzona® 1111 (Super Metal)

Belzona® 9341 (Reinforcement Tape)

SUBSTRATE

Cast Iron

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet ENC-1.

BELZONA FACTS

Belzona was chosen as being the quickest, simplest and cheapest method of conducting the repair. Other alternatives would have involved welding, which the client did not want to pursue due to the age of the casting. The repair needed to be carried out quickly as the car was to go on show the following day. The total cost was around £15 (\$28) to complete.

PICTURES

1. The engine block
2. The exterior of this fully restored classic car
3. The cars interior
4. The rear view of the car



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve