

BELZONA RINGS A TUNE

CUSTOMER

University in Southern California, USA

APPLICATION DATE

August 2004

APPLICATION SITUATION

161-foot bell tower

PROBLEM

Roof leaks

PRODUCTS

Belzona® 3111 (Flexible Membrane)

SUBSTRATE

Concrete

APPLICATION METHOD


Application was carried out in accordance with Belzona Know-How System Leaflet RPA-8.

BELZONA FACTS

The roof area is approximately 30 square feet with a hatch opening. Customer had been advised that the roof should be removed to be repaired. Belzona® 3111 was used to repair the roof in place, saving significant amounts of money.

PICTURES

1. The bell tower
2. Leaks were allowing water to ingress the bells bellow
3. Problems clearly evident
4. Completed roof repair



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve