

BELZONA FLOATING ROOF REPAIR

CUSTOMER

Oil refinery, Egypt

APPLICATION DATE

December 2004

APPLICATION SITUATION

Floating roof - crude oil tank

PROBLEM

Crude oil leakage through welding seams in the tanks floating roof.

PRODUCTS

Belzona® 2311 (SR-Elastomer)

Belzona® 1291 (ES-Metal)

SUBSTRATE

Steel

APPLICATION METHOD


Application was carried out in accordance with Belzona Know-How System Leaflets TCC-2.

BELZONA FACTS

Belzona® 1291 was used to stop the active leak quickly. The flexibility and quick cure of Belzona® 2311 makes it the ideal choice for these types of applications. The Belzona will not crack from the movement of the roof up and down.

PICTURES

1. General view of the crude oil tank
2. The contaminated area of the floating roof
3. Cleaning the surface
4. Leakage stopped (shown) and in other locations



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve