

BELZONA REPAIRS RUBBER PONTTOON

CUSTOMER

Amusement park - Egypt

APPLICATION DATE

December 2004

APPLICATION SITUATION

Rubber pontoon in a water ride.

PROBLEM

The rubber pontoon was worn out in several areas from the effects of water and impact.

PRODUCTS

Belzona 2121 (D&A Hi-Coat Elastomer)

SUBSTRATE

Rubber

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-9.

BELZONA FACTS

These rubber pontoons are pushed through the lake by strong flow. It was critical and unsafe to use the pontoons in there condition. Belzona 2121 was used to repair the worn out areas and also to protect the pontoon from future damage, saving the cost of new units.

PICTURES

1. General view of the rubber pontoons
2. The worn out pontoons
3. Surface preparation
4. Applying Belzona® 2121 to the damaged areas

1.



2.



3.



4.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com

BELZONA®
Repair • Protect • Improve