

BELZONA REPAIRS LARGE HYDRAULIC RAM

CUSTOMER

Offshore oil company - Egypt

APPLICATION DATE

May 2005

APPLICATION SITUATION

Eight meter hydraulic ram of a transport winch

PROBLEM

Deep and wide scores in many areas of the ram.

PRODUCTS

Belzona® 1121 (Super XL-Metal)

SUBSTRATE

Chromed steel

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-2.

BELZONA FACTS

There were scores in many areas of the ram causing many leakages and fluid losses. Belzona saved the replacement costs of the ram, returning it successfully to service.

PICTURES

1. General view of the hydraulic ram
2. Scores on the ram
3. The ram after repair
4. Finishing the surface then cleaning it

1.



2.



3.



4.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com

BELZONA®
Repair • Protect • Improve