

## BELZONA PROVIDES GREAT RETURN ON INVESTMENT

### CUSTOMER

Building Maintenance Company, South Texas USA

### APPLICATION DATE

July 2005

### APPLICATION SITUATION

Air handler shaft

### PROBLEM

Worn shaft caused air handler to not operate effectively.

### PRODUCTS

Belzona® 1111 (Super Metal)

Belzona® 9411 (Release Agent)

### SUBSTRATE

Steel

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-2.

### BELZONA FACTS

A new shaft would have cost \$2,700. For only \$200 worth of Belzona, the shaft was repaired in place and returned to service quickly. Literally tens of thousands of shafts have been repaired with Belzona providing our customers with a great return on investment.

### PICTURES

1. Worn area of air handler shaft
2. Surface preparation in-situ
3. Cured Belzona® 1111
4. Air handler back in service



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

