

BELZONA RECLAIMS DAMAGED BOWLING ALLEY SIDEPLATE

CUSTOMER

Bowling Centre, Calgary, Alberta, Canada

APPLICATION DATE

November 2005

APPLICATION SITUATION

Damaged side plate on the pin deck

PROBLEM

This damage if not repaired would damage customer bowling balls and lead to loss of sanctioning and income.

PRODUCTS

Belzona® 8111 (Mouldable Wood)

SUBSTRATE

Hardwood maple slabs

APPLICATION METHOD

The method used was similar to rebuilding pitting corrosion on vertical vessel walls, a modified Belzona Know-How System Leaflet TCC-5.

BELZONA FACTS

The customer had tried other non-traditional methods such as body filler and drywall mud all unsuccessful.

PICTURES

1. Damaged hardwood slab, 3/4-inch deep
2. First layer of Belzona® 8111 applied
3. Final layer of Belzona® 8111 after sanding
4. Kick plate reinstalled over damaged area



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

