

BELZONA BUND SEALING TO ENSURE ENVIRONMENTAL COMPLIANCE

CUSTOMER

Commercial Vehicle Repair Shop

APPLICATION DATE

September 2005

APPLICATION SITUATION

Bund floor and walls

PROBLEM

Legislation non-compliance due to newly constructed bund being porous due to construction materials, concrete base and 9 inch concrete block walls.

PRODUCTS

Belzona® 4141 (Magma-Build)

Belzona® 4131 (Magma-Screed)

Belzona® 5231 (SG Laminate)

SUBSTRATE

Concrete

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet TCC-15.

BELZONA FACTS

Original condition of bund meant that it failed the Environmental compliance guidelines (PPG 2). Belzona materials were easily applied to give a long term impermeable coating system.

PICTURES

1. Porous bund floor and side wall
2. Introduction of wall to wall fillets
3. Wall penetrations sealed and fillet complete
4. Finished job

1.



2.



3.



4.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve