

BELZONA FOR THE REPAIR OF STEP NOSINGS

CUSTOMER

Furniture manufacturer in North Carolina U.S.A.

APPLICATION DATE

May 2000

APPLICATION SITUATION

Steps at a furniture manufacturing facility leading to a loading area.

PROBLEM

The step nosings leading to a loading area became rounded from constant traffic and improper handtruck usage.

PRODUCTS

Belzona® 4111 (Magma Quartz)

Belzona® 4411 (Granogrip)

SUBSTRATE

Concrete

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

BELZONA FACTS

The leading edges of steps take a tremendous beating, and the Belzona material has a combination of adhesive as well as the compressive strength in order to provide a long lasting solution.

PICTURES

1. Damage to step nosings
2. Belzona® 4911 (TX Conditioner) applied to steps
3. Peeling tape off to reveal Belzona® 4411
4. Completed application



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve