

BELZONA KEEPS ENTRANCE WAY STEPS LOOKING GOOD AND SAFE

CUSTOMER

Agency building - Houston, Texas U.S.A.

APPLICATION DATE

April 1985

APPLICATION SITUATION

Step nosings along a very visible entrance way.

PROBLEM

Various non-skid materials had previously been applied to the nosings of these quarry tile steps with no long-term success.

PRODUCTS

Belzona® 4411 (Granogrip)

Belzona® 9221 (Surefoot Aggregate)

SUBSTRATE

Quarry Tile

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

BELZONA FACTS

Belzona® 4411 was applied by brush in conjunction with Belzona® 9221 on the nosings of the quarry tile steps. 1/4 inch tape was cut and placed over the grout lines of the tile to simulate the quarry tile appearance. This area is high visibility for visiting dignitaries and tourists, so emphasis was placed on safety and cosmetics.

PICTURES

1. Pulling the tape while the Belzona® 4411 is still wet
2. View of entire area
3. Close-up view of completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com

