

BELZONA HEALS HOSPITAL EXPANSION JOINTS

CUSTOMER

Hospital in North Carolina, U.S.A.

APPLICATION DATE

July 1993

APPLICATION SITUATION

Deteriorated expansion joints throughout hospital hallways.

PROBLEM

Deteriorated expansion joints cause problems with x-ray equipment as well as with individuals tripping throughout the hallways.

PRODUCTS

Belzona® 4131 (Magma Screed)

Belzona® 4411 (Granogrip)

Belzona® 2211 (MP Hi-Build)

SUBSTRATE

Concrete

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets FPA-5 and FPA-6.

BELZONA FACTS

In all, seven joints have been refurbished using this Belzona System. This particular facility is a long term user of various Belzona Systems and was aware of the longevity of Belzona repairs.

PICTURES

1. Joint indentation evident through carpet
2. Concrete nosings spalled from traffic
3. Nosing rebuilt and joint sealed
4. Completed application ready for traffic



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve