

## BELZONA REPAIRS AND PROTECTS AUTO REPAIR SHOP FLOOR

### CUSTOMER

Auto Repair Center in Northern Florida - U.S.A.

### APPLICATION DATE

May 2003

### APPLICATION SITUATION

Parts & Battery Storage Area

### PROBLEM

Floor area damaged due to exposure to sulfuric acid.

### PRODUCTS

Belzona® 4131 (Magma-Screed)

Belzona® 5811 (Immersion Grade)

### SUBSTRATE

Concrete

### APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 and TCC-15.

### BELZONA FACTS

The facility is over 30 years old and the customer had made several attempts to repair the floor. In each case, they used some type of concrete repair products to make the repair and coat with several types of paint. Each method was more expensive than the Belzona repair and none were effective.

### PICTURES

1. Prior to application
2. Prepared floor
3. Belzona® 4131 (Magma-Screed) and Belzona® 5811 applied to protect application area long term



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve