

BELZONA PROTECTION TO BUTANE TANK BASE

CUSTOMER

International Petroleum Company - Australia

APPLICATION DATE

2002

APPLICATION SITUATION

Insulated tank containing Butane at -6°C (21°F).

PROBLEM

Corrosion at base of tank. At same time, timber supports were being renewed.

PRODUCTS

Belzona® 3211 (Lagseal)

SUBSTRATE

Steel, Concrete and Timber

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet GSS-3.

BELZONA FACTS

Belzona application creates a flexible, waterproof but microporous seal at junction of tank and base to provide long-term corrosion protection.

PICTURES

1. General view of the tank
2. Preparation of tank and base underway. Tank jacked up ready to install new timbers
3. Application underway
4. Application being completed

1.



2.



3.



4.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com

BELZONA®
Repair • Protect • Improve