

SLOPED SURFACE MADE SAFE WITH BELZONA

CUSTOMER

Commercial Business Park in Albuquerque, New Mexico U.S.A.

APPLICATION DATE

September 2001

APPLICATION SITUATION

Walkway entrance to office building.

PROBLEM

Sloped walkway with exposed aggregate became very slippery when wet, creating a safety hazard.

PRODUCTS

Belzona® 4411 (Granogrip)

SUBSTRATE

Concrete with exposed aggregate

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

BELZONA FACTS

The non-slip system remains in perfect condition after several years. The potential for slippage is alleviated.

PICTURES

1. The slope walkway entrance was very slippery when wet.
2. The pattern is created as tape is being laid.
3. Application of the Belzona® Non-Slip System in progress.
4. The finished non-slip system; the pedestrian area is made safe.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve