

NEW BELZONA FLOOR SURFACE FOR WORKSHOP

CUSTOMER

Engineering company in Portugal

APPLICATION DATE

2002

APPLICATION SITUATION

Floors in engineering workshop containing machine tools.

PROBLEM

Previous floor coverings constantly failing and requiring regular maintenance. Floor cracked and generally in poor condition.

PRODUCTS

Belzona® 4131 (Magma-Screed)

SUBSTRATE

Concrete

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1

BELZONA FACTS

Belzona® 4131 provides a tough impact and oil resistant surface.

PICTURES

1. Belzona® 4911 (Magma TX Conditioner) being applied to ensure maximum adhesion
2. Application of Belzona® 4131 underway
3. Completed application
4. Another view of completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve