

## CUSTOMER GOES NUTS OVER BELZONA FLOOR REPAIRS

### CUSTOMER

Pecan Processing facility in Las Cruces, New Mexico U.S.A.

### APPLICATION DATE

November 2001

### APPLICATION SITUATION

Factory Floor

### PROBLEM

Epoxy overlay of concrete floor in processing plant was disbonded in many places.

### PRODUCTS

Belzona® 4131 (Magma-Screed)

### SUBSTRATE

Concrete

### APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

### BELZONA FACTS

The floor was soaked with pecan oil making the application very difficult. A detergent wash was used on the floor followed by an odorless degreaser followed by mechanical abrasion. This was followed by another degreasing. The pecan factory was so pleased with these initial repairs that they purchased additional material and continue to address other floor problem areas as they arise. After several years all repairs are holding up very well.

### PICTURES

1. Cleaning.
2. Surface preparation.
3. Application.
4. Finished.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

