

BELZONA REPAIRS TO FLOATING HOSE

CUSTOMER

Oil Company

APPLICATION DATE

December 1998

APPLICATION SITUATION

24" Yokohama floating hose.

PROBLEM

Extensive damage to the rubber flotation.

PRODUCTS

Belzona® 2211 (MP Hi-Build Elastomer)

Belzona® 2221 (MP Fluid Elastomer)

SUBSTRATE

Rubber

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet SOS-12.

BELZONA FACTS

Inspected February 2000 hose still in good condition. Repair cost \$3,000; new hose cost about \$70,000.

PICTURES

1. The extent of the damage clearly evident.
2. Application of Belzona® 2221.
3. Completed application.



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve