

BELZONA PROTECTS COOLING WATER SPOOLS

CUSTOMER

Power station - Ireland

APPLICATION DATE

2003

APPLICATION SITUATION

Main cooling water intake pipework.

PROBLEM

Previous coating was badly damaged allowing severe erosion-corrosion on pipework internals.

PRODUCTS

Belzona® 1341 (Supermetalgilde)

SUBSTRATE

Steel

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-2.

BELZONA FACTS

Some spools were so badly corroded that they had to be replaced or sleeved. The Belzona® 1341 coating will prevent future costly replacement becoming necessary.

PICTURES

1. General view of the spools
2. Degree of original erosion clearly evident
3. Application underway
4. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve