

## SOAP POWDER CAN'T WASH BELZONA AWAY!

### CUSTOMER

Manufacturer of washing powder in Italy

### APPLICATION DATE

On-going since 2002

### APPLICATION SITUATION

Soap Mixer

### PROBLEM

Corrosion from the soap powder and water mixture damages the housing and rotating elements of the mixer.

### PRODUCTS

Belzona® 4311 (Magma CR1)

### SUBSTRATE

Cast Steel

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-3.

### BELZONA FACTS

The customer is pleased with the performance of the Belzona coating and there is an on-going program to protect these mixers.

### PICTURES

1. The mixer as it arrives
2. The coated rotating elements
3. The mixer end covers coated
4. The mixer body coated



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve