

WATERPROOFING CHIME ANGLE WITH BELZONA

CUSTOMER

Power Plant - Texas USA

APPLICATION DATE

May 2004

APPLICATION SITUATION

Tank Chime Angle

PROBLEM

Corrosion was occurring on steel/concrete interface of wastewater tank and pad.

PRODUCTS

Belzona® 3111 (Flexible Membrane)

Belzona® 3921 (PSC Surface Conditioner)

Belzona® 9311 (Membrane Reinforcing Sheet)

SUBSTRATE

Steel and concrete

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet GSS-3.

BELZONA FACTS

Customer had used Belzona® 3111 on many other water proofing repairs. Numerous attempts using caulking materials did not stand up to the requirements.

PICTURES

1. Close look at the problem area
2. Prepared surface taped off
3. Application completed



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

