

## KITCHEN SAFETY IMPROVED THANKS TO BELZONA

### CUSTOMER

School in UK

### APPLICATION DATE

July 2002

### APPLICATION SITUATION

Floors in kitchen area

### PROBLEM

Routine health inspection had highlighted hygiene and safety problems with the floor area necessitating refurbishment before the school re-opened.

### PRODUCTS

Belzona® 5231 (SG Laminate)

### SUBSTRATE

Quarry tiles

### APPLICATION METHOD

Two coats of Belzona® 5231 were applied after thoroughly cleaning and grit blasting the existing tiled surface.

### BELZONA FACTS

Belzona® 5231 created a hygienic, seamless floor surface with the right degree of non-slip to provide safe footing for the kitchen staff. The application was completed smoothly in the short holiday period during which the school was closed.

### PICTURES

1. Kitchen area prior to the Belzona application
2. Wash area prior to the Belzona application
3. Belzona® 5231 applied
4. Application completed



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

**BELZONA®**  
Repair • Protect • Improve