

BELZONA® 3211 (LAGSEAL) IN TOUGH ENVIRONMENT - 2ND TIME AROUND

CUSTOMER

Power plant in Texas, USA

APPLICATION DATE

2004

APPLICATION SITUATION

Coating on insulated caustic storage tank

PROBLEM

After eight years of service the previously applied Belzona® 3211 was ready for replacement. The Belzona Membrane System performed so well in its first eight years, the customer naturally chose Belzona again.

PRODUCTS

Belzona® 3211 (Lagseal)

Belzona® 3921 (GSC Surface Conditioner)

Belzona® 9311 (Reinforcing Membrane Sheet)

SUBSTRATE

Foam insulation over plastic tank

APPLICATION METHOD

Once the old coating was removed, the application proceeded in accordance with Belzona Know-How System Leaflet TCC-4.

BELZONA FACTS

Belzona® 3211 held up well (eight years) in this tough environment. Fumes from neighboring acid tank condensed on a tank, causing rapid deterioration of the previous coatings.

PICTURES

1. View from acid tank
2. Surface preparation
3. Belzona® 3211 applied



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve