

BELZONA STOPS WINDOW LEAKS

CUSTOMER

Community College, St. Charles, Missouri USA

APPLICATION DATE

August 2005

APPLICATION SITUATION

Persistent leaks for several years. Repairs attempted by many people had been unsuccessful.

PROBLEM

The bottoms of the windows had almost imperceptible openings allowing wind blown water to enter and travel to the entry canopy staining the ceiling tile.

PRODUCTS

Belzona® 3111 (Flexible Membrane)

SUBSTRATE

Concrete and steel

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-3.

BELZONA FACTS

The current director of facilities had used Belzona® 3111 over 20 years ago to stop leaks around a chimney and it is still leak free, so the customer had every confidence in the chosen solution.

PICTURES

1. View of windows above entry canopy.
2. Close up of the problem and start of the repair.
3. Finished repair.



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com

BELZONA®
Repair • Protect • Improve