

BELZONA REPAIRS NATURAL GAS VALVE

CUSTOMER

Oil and gas production company, Egypt

APPLICATION DATE

February 2003

APPLICATION SITUATION

Natural gas valve

PROBLEM

Gas leaks had been worsened by traditional weld repairs.

PRODUCTS

Belzona® 1111 (Super Metal)

SUBSTRATE

Cast iron

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-1.

BELZONA FACTS

Belzona successfully solved this serious problem with a simple and fast technique, avoiding heat distortion to the surface and at a low cost.

PICTURES

1. General view of the valve.
2. Traditional welding failed causing more leakage.
3. Surface preparation.
4. Application completed.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve