

BELZONA HELPS SWEET MANUFACTURER AGAIN AFTER 8 YEARS

CUSTOMER

Sweet Manufacturer, Belgium

APPLICATION DATE

September 2005

APPLICATION SITUATION

Mixing tank

PROBLEM

The Belzona coating, applied 8 years previously, was still in good condition and had only suffered some discolouration. The client, however, wanted to apply a fresh coat of Belzona.

PRODUCTS

Belzona® 1321 (Ceramic S-Metal)

SUBSTRATE

Steel & Belzona® 1321

APPLICATION METHOD

The Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

BELZONA FACTS

The client was so pleased that the original Belzona coating lasted 8 years that they once again contacted Belzona to re-coat the machine.

PICTURES

1. 8-year-old Belzona® 1321 coating
2. Another view of 8-year-old Belzona® 1321 coating
3. New Belzona® 1321 coating
4. Coated hatch



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>