

## BELZONA KEEPS ENTRANCE WAY NICE AND SAFE

### CUSTOMER

Theme Centre, Doncaster, UK

### APPLICATION DATE

2002

### APPLICATION SITUATION

Timber Decking

### PROBLEM

Slippage problem, especially on the main entrance of the building. The client had tried unsuccessfully to combat the problem by nailing chicken wire to the timber decking, which caused extra trip hazards.

### PRODUCTS

Belzona® 5811 (Immersion Grade)

Belzona® 9221 (Surefoot Aggregate White)

### SUBSTRATE

Wood

### APPLICATION METHOD

The application was carried out using a modified version of the Belzona Know-How System Leaflet FPA-8. The Belzona® 5811 was mixed with 50% of Belzona® 9221.

### BELZONA FACTS

Following this initial area being treated a water spillage occurred half on the decking and half on the Belzona Deck Grip. It was noted that the timber decked area was extremely slippery and hazardous whereas the area covered with the Belzona Deck Grip gave excellent grip properties even when soaked with water.

### PICTURES

1. Slippage problem area.
2. After masking 2 out of 6 grooves, Belzona® 5811 was mixed with 50% aggregate applied.
3. Masking being removed from completed application.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

