

BELZONA PROTECTS MIXING TANK

CUSTOMER

Dairy in Oklahoma, USA

APPLICATION DATE

March, 2006

APPLICATION SITUATION

During expansion, the large dairy constructed a new water plant to treat their own water (average 400,000 GPD).

PROBLEM

Customer needed protection on their KMnO_4 (Potassium Permanganate) mixing tank.

PRODUCTS

Belzona® 5811 (Immersion Grade)

Belzona® 4111 (Magma Quartz)

SUBSTRATE

Concrete

APPLICATION METHOD



Application was carried out in accordance with a modified version of Belzona Know-How System leaflet TCC-15.

BELZONA FACTS

Customer choose Belzona based on success of previous applications.

PICTURES

1. Bare unprotected mixing tank.
2. Surface prepared and holes patched with Belzona® 4111.
3. First coat Belzona® 5811 being applied.
4. Final coat Belzona® 5811 applied.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

