

## BELZONA RE-SURFACES WATER PARK FLOORS

### CUSTOMER

Water Park - Oklahoma

### APPLICATION DATE

May 2007

### APPLICATION SITUATION

Bathroom floors and outside surfaces in a water park.

### PROBLEM

Painted floors in bathrooms and outside surfaces were wearing out on a yearly basis and the city was looking for a long term solution.

### PRODUCTS

Belzona® 5111 (Ceramic Cladding)

Belzona® 9221 (Surefoot Aggregate White)

### SUBSTRATE

Concrete

### APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

### BELZONA FACTS

Belzona product was found to provide a long term solution compared to original paint system which required annual replacement.

### PICTURES

1. Bathroom floors before application.
2. Bathroom floors after Belzona® 5111 was applied.
3. Outside surfaces before application.
4. Outside surfaces after Belzona® 5111 application.



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve