

BELZONA REPAIRS TO ROOFTOP EXHAUST DUCTING

CUSTOMER

Pet food manufacturer, MO

APPLICATION DATE

April 2007

APPLICATION SITUATION

Rooftop exhaust ductwork

PROBLEM

Joints were leaking allowing escape of unpleasant gases into the neighbourhood leading to many complaints.

PRODUCTS

Belzona® 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Galvanized metal

APPLICATION METHOD

Application carried out using a modified Belzona Know-How System Leaflet VPF-11a

BELZONA FACTS

Years of successful repairs, some of them very difficult, gave client the confidence to proceed with Belzona repairs.

PICTURES

1. First duct joint
2. Close up of first joint repair
3. Second joint repair



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve