

BELZONA RESTORATION OF HISTORIC FEDERAL BUILDING

CUSTOMER

Pensacola, Florida

APPLICATION DATE

September 2006

APPLICATION SITUATION

Copper gutters of historic site. Gutter system is part of the original structure and it is not permitted by the Federal Government to change materials.

PROBLEM

The copper gutters had to be maintained watertight without replacement.

PRODUCTS

Belzona® 3111 (Flexible Membrane) fully reinforced system

SUBSTRATE

Copper

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-6. Power wire brushing and degreasing was carried out prior to application.

BELZONA FACTS

There was no way to replace the copper gutter system as dictated by the Federal Government. Alternatives such as silicone sealants would not provide required longevity. Belzona® 3111 was chosen due to the ability to coat the copper gutter system and maintain its functionality without removal. It maintained appearance to the satisfaction of the engineers.

PICTURES

1. Belzona® 3111 being applied
2. Belzona initially applied to gutter seams
3. View of the finished gutter system coated with Belzona® 3111
4. Another view of the finished gutter system coated with Belzona® 3111



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve