

BELZONA REFURBISHES MILITARY DOG KENNELS

CUSTOMER

Military Base, North Alabama

APPLICATION DATE

April 2006

APPLICATION SITUATION

Floors and walls in dog kennels.

PROBLEM

An easy to clean, hygienic non slip coating required.

PRODUCTS

Belzona® 4111 (Magma Quartz) Belzona® 5111 (Ceramic Cladding)
Belzona® 5811 (Immersion Grade)

SUBSTRATE

Concrete and Cinder Block

APPLICATION METHOD

This application was performed in accordance with Belzona Know-How System Leaflets FPA-3 & TCC-15. To create a non-slip surface that did not damage paws, different aggregates were tried before settling on a non-standard Belzona one that was found to be ideal. Coves between wall and floor were formed and Belzona® 5111 provided stain resistant finish.

BELZONA FACTS

The Commander tried many different coatings over the years and had not found a suitable coating that stood up to the wear and tear of the dogs. Our Belzona application has been down for 2 years and looks just like new.

PICTURES

1. Prepped and ready to coat
2. Floor and coves covered
3. Almost complete, walls being coated
4. All done! Ready to turn over to the owners



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve