

BELZONA FLEXIBLE MEMBRANE SEALS LEAKING CONCRETE DECK

CUSTOMER

Property Management Company

APPLICATION DATE

August 1995

APPLICATION SITUATION

Leaking concrete deck over parking garage

PROBLEM

Water, leaking through the concrete deck, was falling on the cars parked beneath and damaging the paintwork

PRODUCTS

Belzona® 3111 (Flexible Membrane)

SUBSTRATE

Exposed aggregate concrete

APPLICATION METHOD

Application completed in accordance with a modified version of Belzona Know-How System Leaflet RPA-10.

BELZONA FACTS

Various crack sealing products had been tried with little little to no success. A recent check in 2008 reveals the deck coating to still be in service.

PICTURES

1. The deck prepared by pressure washing
2. After application of Belzona® 3911 to concrete surfaces and Belzona® 3921 Aluminum surfaces (window and door frames), Belzona® 3111 was applied
3. View of deck taken in 2005 after 10 years of service



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve