

BELZONA PROTECTS AERATOR IN WATER TREATMENT PLANT

CUSTOMER

Waste Water Treatment Plant, British Columbia

APPLICATION DATE

November 2007

APPLICATION SITUATION

Aerator in water treatment process.

PROBLEM

The welded component required protection from bi-metallic corrosion

PRODUCTS

Belzona® 1321 (Ceramic S Metal)

SUBSTRATE

Stainless Steel

APPLICATION METHOD


Application completed in accordance with Belzona Know-How System Leaflet SHM-11.

BELZONA FACTS


A similar piece of equipment built 6 years previously and protected with Belzona® 1321 had provided extremely good service.

PICTURES

1. Completed aerator unit in the fabricating shop after grit blasting
2. Close up view of the equipment
3. Completed application, 2 coats of Belzona® 1321
4. Protected aerator in service



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve