

## BELZONA STEP NOSING REPAIR

### CUSTOMER

Racecourse, Liverpool, England

### APPLICATION DATE

March 2007

### APPLICATION SITUATION

Damaged step nosings.

### PROBLEM

Porters had been bouncing beer barrels down the steps from the bar situated on the floor above. This was damaging the concrete step nosings.

### PRODUCTS

Belzona® 4111 (Magma Quartz)

Belzona® 4411 (Granogrip)

### SUBSTRATE

Concrete

### APPLICATION METHOD



Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & -8.

### BELZONA FACTS

Belzona was chosen due to its high bond strength, impact resistance and hard wearing non-slip surface proven in similar environments.

### PICTURES

1. Steps showing signs of damage
2. Close up of damage
3. Steps repaired
4. Close up of repair



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve