

BELZONA ELASTOMER SEALS CONCRETE PARKING DECK

CUSTOMER

Shopping Mall - Vancouver, BC

APPLICATION DATE

November 2007

APPLICATION SITUATION

Various cracks and faulty seams on concrete parking deck.

PROBLEM

A previous application by another contractor had failed in a very short space of time leading to water entering the shop below.

PRODUCTS

Belzona® 2221 (MP Fluid Elastomer)

SUBSTRATE

Concrete

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-6.

BELZONA FACTS

Heavy rains after the application had been completed revealed that the area was now completely water-tight.

PICTURES

1. All joints were ground clean to remove all traces of the failed material
2. All joints were conditioned with Belzona® 2911 prior to injecting the Elastomer
3. Completed application with all the joints and cracks sealed



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve