

## BELZONA HOT OFF THE PRESS

### CUSTOMER

Regional Newspaper, Leeds, UK

### APPLICATION DATE

May 2007

### APPLICATION SITUATION

Conveyor belt carrying rejected newspapers.

### PROBLEM

Large hole torn in the belt caused by a metal tool being dropped onto the belt.

### PRODUCTS

Belzona® 2311 (SR Elastomer)

### SUBSTRATE

Rubber

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-1.

### BELZONA FACTS

Due to the nature of the customers business and the need for this particular belt to be running almost 24 hours a day seven days a week, it was impossible to replace the belt and would cost around £3000. Utilising the Belzona system it cost them around £40 in materials and they got the belt back up and running within 2 hours, in time for the next print run.

### PICTURES

1. Damaged belt
2. Preparation in progress
3. Finished application, with customer admiring his work



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve