

## BELZONA PROTECTS HOT WATER TANKS

### CUSTOMER

State Correctional Facility, Missouri

### APPLICATION DATE

February 2007

### APPLICATION SITUATION

Hot water generation tanks within the Powerhouse.

### PROBLEM

Severe internal corrosion

### PRODUCTS

Belzona® 5811 (Immersion Grade)

Belzona® 1111 (Super Metal)

### SUBSTRATE

Steel

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

### BELZONA FACTS

This application saved over \$60,000 against cost of replacement.

### PICTURES

1. The tank inside the Powerhouse
2. View of the internal corrosion
3. Contractor applying 2<sup>nd</sup> coat of Belzona® 5811
4. Technical Consultant inside the finished tank 2 days later



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve