

## EXPANSION JOINT AT HOSPITAL SEALED WITH BELZONA

### CUSTOMER

Hospital, Missouri

### APPLICATION DATE

2007

### APPLICATION SITUATION

Expansion joints in corridor in need of repair

### PROBLEM

Expansion joints in the hospital had become a tripping hazard

### PRODUCTS

Belzona® 4111 (Magma Quartz)

Belzona® 2221 (MP Fluid Elastomer)

### SUBSTRATE

Concrete

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-5 and -6.

### BELZONA FACTS

The hospital needed a fast-curing and reliable method for repairing expansion joints that were creating trip hazards for patients.

### PICTURES

1. View of joint with kick plate removed
2. Application of Belzona® 4111
3. Application of Belzona® 2221
4. Completed application



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve