

BELZONA REFURBISHES LABORATORY WORKTOPS

CUSTOMER

State Health Dept.

APPLICATION DATE

March 2005

APPLICATION SITUATION

State Health Dept was building new facility and needed to extend life of existing facility lab counter tops

PROBLEM

Severely degraded counter tops needed to be resurfaced with a chemically resistant coating.

PRODUCTS

Belzona® 5811 (Immersion Grade)

SUBSTRATE

unknown

APPLICATION METHOD


Application carried out in accordance with modified Belzona System leaflet FPA-3. Special care was taken to clean sand the surfaces. Belzona® 5811 applied over-thickness with a trowel to create a self levelling coat.

BELZONA FACTS

Saved tens of thousands of dollars on replacements. In December 2007 Facilities Manager reports all is well, no complaints from workers.

PICTURES

1. Sink in lab before work
2. Fume cupboard before work
3. Sink after coating
4. Counter top after coating



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

