

## BELZONA EXTENDS RUBBER PUMP LINER LIFE

### CUSTOMER

Power Station, Poland

### APPLICATION DATE

2005

### APPLICATION SITUATION

Warman pump circulating Gypsum slurry

### PROBLEM

The rubber liner had limited life (up to 5 years). New liner cost 40,000 EUR

### PRODUCTS

Belzona® 2121 (D&A Hi-Coat Elastomer)

### SUBSTRATE

Rubber

### APPLICATION METHOD


Application was carried out in accordance with Belzona Know-How System Leaflet CEP-3.

### BELZONA FACTS

New liner costs 40,000 EUR. Belzona coating cost 3,000 EUR and after 3 years in service shows no significant wear.

### PICTURES

1. General view of the pump
2. First coat applied
3. Second coat
4. completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve