

## BELZONA REPAIRS A VERY LARGE PUMP HOUSING

### CUSTOMER

Power Plant, France

### APPLICATION DATE

July 2002

### APPLICATION SITUATION

Large cooling water pump housing

### PROBLEM

Water infiltration between joint of metal and concrete

### PRODUCTS

Belzona® 1111 (Super Metal)

### SUBSTRATE

Steel and Concrete

### APPLICATION METHOD

The application was carried out in accordance with a modified Belzona Know-How System Leaflet CEP-5.

### BELZONA FACTS

Other solutions were considered implausible by the client who was delighted when Belzona® came up with a solution

### PICTURES

1. Application Situation
2. Cleaning
3. Application of Belzona® 1111

1.



2.



3.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve