

## BELZONA REPAIRS VULCANIZED RUBBER LINED PUMP

### CUSTOMER

Chemical Plant, Italy

### APPLICATION DATE

April 2006

### APPLICATION SITUATION

Vulcanized rubber lined pump body

### PROBLEM

A large area of the rubber had been eroded away.

### PRODUCTS

Belzona® 2111 (D&A Hi-Build Elastomer)

### SUBSTRATE

Vulcanized rubber

### APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-11.

### BELZONA FACTS

Belzona Elastomer outlasted the original rubber and allowed localized repairs to be carried out on site without having to return the pump for re-vulcanizing.

### PICTURES

1. Pump body before application
2. Close up of damaged rubber
3. Upper body after application
4. Lower body after application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

