

BELZONA REPAIRS BIODIESEL COLUMN

CUSTOMER

Biodiesel Producer, Memphis, TN

APPLICATION DATE

November 2006

APPLICATION SITUATION

Biodiesel Column

PROBLEM

Due to stress on a flange there was a crack at the weld causing Biodiesel to leak. This was 130 feet above the ground.

PRODUCTS

Belzona® 4301 (Magma CR1 Hi-Build)

SUBSTRATE

Stainless Steel

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-3 & 6.

BELZONA FACTS

The Belzona solution offered the customer quick turn-around, without the expense of having to empty the column which they would have had to do if welding.

PICTURES

1. The column to be repaired
2. Column under repair
3. Repaired area on column
4. Repaired area close-up



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve