

BELZONA REPAIRS SCHOOLS CHILLER

CUSTOMER

Elementary School, St. Louis, Missouri

APPLICATION DATE

2007

APPLICATION SITUATION

Corroded chiller face

PROBLEM

Years of service had caused extensive corrosion on the chiller tube sheet face.

PRODUCTS

Belzona® 1311 (Ceramic R-Metal)

Belzona® 1321 (Ceramic S-Metal)

SUBSTRATE

Carbon Steel

APPLICATION METHOD

Application was completed in accordance with Belzona System Leaflet HEX-1.

BELZONA FACTS

School officials were aware of Belzonas reputation for quality and reliability.

PICTURES

1. Corroded tube sheet face
2. Application in progress
3. Completed application
4. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com

BELZONA®
Repair • Protect • Improve