

BELZONA PROTECTS CONTAINMENT AREA

CUSTOMER

Power Project - Bastrop, Texas, USA

APPLICATION DATE

November 2007

APPLICATION SITUATION

Containment area for water treatment chemicals.

PROBLEM

The previous coating had failed causing significant damage to the underlying concrete.

PRODUCTS

Belzona® 4111 (Magma Quartz)

Belzona® 4311 (Magma CR1)

SUBSTRATE

Concrete

APPLICATION METHOD

The application was carried out in accordance with Belzona System Leaflets TCC-9 & 15

BELZONA FACTS

Previous attempts to coat this area had failed due to the chemical concentration. Belzona was chosen for its high chemical resistance. The two color system was also seen as an advantage as it will show when the coating needs to be touched up.

PICTURES

1. Containment area prior to being coated
2. Area prepared and leveled with Belzona® 4111
3. First coat of Belzona® 4311 being applied
4. Completed application



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve