

BELZONA RESTORES KITCHEN WASHROOM FLOOR

CUSTOMER

Hospital - Albuquerque, New Mexico, USA

APPLICATION DATE

October 2007

APPLICATION SITUATION

Hospital kitchen washroom floor

PROBLEM

The terrazzo floor had degraded from constant cleaning and contact with cleaning solutions.

PRODUCTS

Belzona® 4111 (Magma Quartz)

Belzona® 5231 (SG Laminate)

SUBSTRATE

Terrazzo

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. Belzona® 5231 was applied and extra grit broadcast on top.

BELZONA FACTS

A competitive bid was placed for the removal of existing surface and new terrazzo floor applied. Belzona was faster, cleaner, and less expensive than the other process.

PICTURES

1. Close-up of original damaged floor
2. Heavy damage in washdown room
3. Finished floor where washing machine goes
4. Finished floor from outside hallway



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve