

## BELZONA REPAIRS AND SEALS IRON GUTTER

### CUSTOMER

Logistics Factory, Lancashire - UK

### APPLICATION DATE

April 2007

### APPLICATION SITUATION

Traditional cast iron gutter 0.5 meters wide by 64 meters long

### PROBLEM

The cast iron had over time corroded and the joints deteriorated allowing water to enter the internal fabric of the building.

### PRODUCTS

Belzona® 3111 (Flexible Membrane)

Belzona® 3921 (GSC Conditioner)

Belzona® 9311 (Reinforcing Sheet)

### SUBSTRATE

Cast Iron

### APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-6.

### BELZONA FACTS

The cost of the Belzona was a fraction of the replacement cost of the cast iron gutter which was the other alternative.

### PICTURES

1. Blocked and corroded gutter
2. Gutter drained ready for preparation
3. Belzona fully reinforced Flexible Membrane system
4. Completed application



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve